

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
PA  
11-SCA.  
1-E-

HAER No. PA-184-E

Eureka No. 40, Tipple and Cleaning Plant  
Berwind-White Coal Mining Company  
E of PA 56, N of Little Paint Creek  
Scalp Level  
Cambria County  
Pennsylvania

Jet Lowe, Photographer, March 1988

- |             |  |
|-------------|--|
| PA-184-E-1  | GENERAL VIEW FROM BONY PILE LOOKING SOUTH. WASH HOUSE IN LEFT BACKGROUND. TIPPLE AND CLEANING PLANT TO RIGHT. IN CENTER IS A TANK USED FOR TREATING MINE REFUSE AND ACID RUNOFF. |
| PA-184-E-2  | GENERAL VIEW LOOKING WEST, TIPPLE AND CLEANING PLANT TO RIGHT, TREATMENT TANK IN CENTER.   |
| PA-184-E-3  | VIEW OF EAST AND NORTH SIDE OF TIPPLE AND CLEANING PLANT LOOKING SOUTHWEST.  |
| PA-184-E-4  | VIEW OF SOUTH SIDE OF TIPPLE AND CLEANING PLANT LOOKING NORTH. TO LEFT IS CAR REPAIR SHOP AND POWER PLANT.   |
| PA-184-E-5  | VIEW OF SOUTH AND EAST SIDE LOOKING NORTHWEST  |
| PA-184-E-6  | VIEW OF WEST AND SOUTH SIDES LOOKING NORTHEAST   |
| PA-184-E-7  | VIEW OF WEST AND SOUTH ELEVATION LOOKING NORTHEAST   |
| PA-184-E-8  | VIEW OF WEST SIDE OF TIPPLE AND CLEANING PLANT, PANGBORN DUST COLLECTOR IN FOREGROUND.   |
| PA-184-E-9  | VIEW OF WEST SIDE OF TIPPLE AND CLEANING PLANT   |
| PA-184-E-10 | DETAIL OF TIPPLE SHOWING ROTARY CAR DUMP (MANUFACTURED BY HEYL AND PATTERSON INC., PITTSBURGH, PA).  |
| PA-184-E-11 | VIEW OF SOUTH AND EAST SIDES OF TIPPLE LOOKING NORTHWEST   |
| PA-184-E-12 | VIEW OF NORTH SIDE OF TIPPLE HOUSE LOOKING SOUTHWEST   |